	Approved Fo	r Release 2003/11/19 : CIA-RDP63-00313 ∆ 000500060004-7
1		· · ·
25X1A		24.03-63 3.07 & 63
		18 Harch 1963
25X1A	SETAMOU PO	
	The state of the s	1 CHOSET Magine and Main Paul Control Following
		1 2167-63, dated 29 January 1963 titled "TENGART Regime Delivery Status"
		can angines have been delivered of which fourteen are light operation.
	2. Five miditional angines are scheduled for delivery by 31 March. Because of pacing main fund controls, only two of these five engines can be delivered providing controls are delivered according to latest provides.	
	3. Engines # 218, # 219, and # 220 are ready for final test but short controls. Engine # 218 has been waiting at final test for a control since 24 Sebruary.	
	instillty to define and resolve central functional and test facility instrumentation problems arising during acceptance test in the face of instrumentation problems arising during acceptance test in the face of instrumentation problems arising during acceptance test in the face of instrument has instillty reflects a failure to properly plan for and stay up to the instrument level of activity required in embination with the increased level of accuracy desired in order to support the angine delivery program. As indicated in paragraph 5 of reference acceptances. Hamilton-Standard has been more of the increased level of test activity requirement since on or before 2t January 1963.	
2EV4A		
25X1A		Sevelopment Sivicion
25X1A	CC: AFTOO_S PD/OSA Distribution: 1-DD/R	

6-TAES/OSA
7-AFICO-S
8-RB/OSA
Approvédificas de 2003/11/19 : CIA-RDP63-00313A000500060004-7

Gentrol System

25X1A